Shape Corp GTR09 NA vs EU Vehicle Modified Round Robin



Shape Corp Flex PLI Testing

- 1. Vehicle #1 Test Setup
- 2. Vehicle #1 EU & NA
- 3. Vehicle #2 Test Setup
- 4. Vehicle #2 EU & NA + IWG RR Tests
- 5. General Testing Observations
- Ground Line Adjustment Required in CAE

Legform Detail


| SN | Version | Status* | Mass | Owner |
|------|----------|---------|---------|------------|
| SN01 | Flex GTR | Master | 13.32kg | Humanetics |
| VRTC | Flex GTR | Master | 13.18kg | NHTSA |


Master = Latest eng level (bone cores/long rubber) & meets cert corridors



Vehicle #1

Test Locations







NA vehicle w/ EU system applied

^{*}Offset location established from EuroNCAP protocol



Vehicle #1: EU & NA








Vehicle #2

Test Locations







*Offset location established from EuroNCAP protocol



Vehicle #2: EU & NA + IWG RR Tests







Shape Corp: General Observations

- Both VRTC & SN01 legforms at "master" level containing updated bone cores, tibia long rubber and within newly defined certification corridors
- Slight launch plate modifications required to keep tibia bending below 10Nm during free flight.
 - (a) bottom plate extension
 - (b) material removed at center for knee joint clearance
- Friction differences in roller bracket required **launch pressure differences** between legs
- Wire exit base/clamp (top of tibia) were **not being used** on either legform (wires loose)
- DAS cable connection **socket damaged** when impacting floor.
- Zipper durability is an issue, several openings occurred during Y-offset tests
- During CAE correlation it was discovered the LS-DYNA Flex PLI Ver2 legform does not include the plastic endcap at tibia bottom. Measurement to ground line should be compensated by 8.6mm (see next page).



Ground Line Adjustment Required in CAE

