EVS GTR IWG #14



September 2017 Bohyun Moon / Chief Researcher



Korea Automobile Testing and Research Institute(KATRI) 200 Samjon-Ro, Songsan-Myun, Hwasung-Si, Gyeonggi-Do, 18247

> The date entry into force : Feb. 2009

Purpose

Evaluation of traction battery safety under Vehicle immersed accident

Test	Procedure	Criteria
Immersion	Immerse into 0.6M salty water for 1hr	No Fire &
		No Explosion



Video clips for Failed water immersion test

This video file is confidential. So, Korea will show the video at only the venue.





➤ Failed case

1

Ignition and explosion immediately after immersion



Causes of Defects


Insufficient for Distance through insulation (DTI) in High voltage battery



➤ Failed case

2

Arcing occurs at power outlet immediately after immersion (relay open) Continuous arcing at Safety plug (Disconnected switch)






➤ Failed case

2

Arcing occurs at power outlet immediately after immersion (relay open) Continuous arcing at Safety plug (Disconnected switch)








➤ Failed case

2


Arcing occurs at power outlet immediately after immersion (relay open) Continuous arcing at Safety plug (Disconnected switch)





Water immersion test

> Number of Vehicle immersed accident in Korea



- Increased accidents caused by localized heavy rains or storms
- Need to consider in the event by immesion during parking



➢ Recommendation

Minimum safety requirements of traction battery are needed under Vehicle immersed accident.

The causes of Vehicle immersed accident are diverse, so multiple researches are needed.





Thank you for attention!

