


Start timing of MRMLC

UNR157-11-06
11^h SIG on R157
09,10 December 2021



Other road user should be warned that ALKS is in emergent situation because **MRM LC** dose not have enough capability of doing LC safely unless other road users specially take care of the ALKS movement.
Without this "5s", other road user has no chance to be warned before the ALKS starts **MRM LC**.