



CRSs installation in row #2 of vehicles of class II & III (behind the driver seat)

IWG-STCBC 8th meeting

10/11/2021



OICA



CRS Rear-facing installation in row#2

ISO/ R2 envelopes



+224 mm





ISO/B2 envelope installation in row#2



+114 mm






ISO/B2 envelope installation in Class II & III rear row seats

+60 mm







Double-deck-Class II/III-vehicles: CRS B2 front-facing installation leads to collision with window pillar on the upper deck







Class III bus with coach seats

Check ISO/B2 lower gangway-collision





Seating position forbidden if Sitsafe is used?



Do we need a specific envelop?