Svensson Bolennarth

Från: Jaumouille Philippe <Philippe.Jaumouille@rtn-goett.com>

Skickat: den 19 maj 2014 17:30 Till: Svensson Bolennarth

Kopia: juergen.westphaeling@tuev-sued.de **Ämne:** RE: Internal approval procedure

Dear Mr Svensson,

I get several information for item 2:

- For AL-KO company, tests for tow bars are basically done following CARLOS TC. Only on specific request of customer, tests are done following CARLOS TC BC (taking in account loading of Bicycle Carrier).
- For stabilizing system like AKS, AL-KO respect ISO norm 11555. That means that torque due to the stabilization is always under 300 Nm. I think that these values are very low compare to efforts of a bicycle carrier.

I will not be able to be in Poland for next meeting but I stay available for any further question.

Best regards.

Philippe JAUMOUILLE Responsable Technique

Société Nouvelle RTN-GOETT SAS ZI Route de Tours BP 41 49490 NOYANT

Téléphone (+33) 02 41 84 10 24 Fax (+33) 02 41 89 32 09

philippe.jaumouille@rtn-goett.com

www.rtn-goett.eu

From: Svensson Bolennarth [mailto:bolennarth.svensson@vbggroup.com]

Sent: Tuesday, February 04, 2014 1:38 PM

To: Jaumouille Philippe

Subject: Internal approval procedure

Dear Mr. Jaumouille,

At an early meeting we agreed that you should send a copy of you internal procedure for drawbars to the chairman. I have not seen that we have got any copy from you. Could you please send a copy to me?

Bolennarth Svensson Business Engineer Coupling Equipment

VBG GROUP

VBG GROUP TRUCK EQUIPMENT AB Box 1216 SE-462 28 Vänersborg

Street address: Herman Kreftings gata 4

Tel +46 521 278126 Fax +46 521 277794 Mobile +46 706 177217

E-mail bolennarth.svensson@vbggroup.com

Disclaimer: The content of this e-mail is intended solely for the use of the Individual or entity to whom it is addressed. If you have received this communication in error, be aware that forwarding it, copying it, or in any way disclosing its content to any other person, is strictly prohibited. If you have received this communication in error, please notify the author by replying to this e-mail immediately.