



VIAQ-31-06 “ OICA recommendation on including Part 4 in the Mutual Resolution No. 3”

The recommendation from OICA is to NOT include part 4 “Outside air pollutants to incoming air” in the mutual resolution of VIAQ as its stated now with existing time plan.

The main reasons are:

- Test conditions hard to fulfill (min level of PM 2.5 etc.)
- Difficult to get reproducible data
- Expensive test equipment needed to perform tests

OICA also recommends to summarize and document the work that has been performed in the IWG on VIAQ and put this on hold. If new pre-requisites that significantly changes the situation occurs, the work can be re-started.