


Width of the Bumper Testing Zone and Legform Protection Area

► Audi A6



Lower Legform protection area

Testing area according to EC 78/2009

Corner of bumper (contact point of 30° plane)

Audi A6 was tested at EuroNCAP twice outside of the bumper testing zone, with green results
 → Audi A6 also fulfills the legislative requirements outside of the theoretical testing area of EC 78/2009